



**Note:** Mount suppressor as close as possible to coils. Only one suppressor is required on the power supply that feeds all four coils.

Mfr Part No. - Mitsubishi H6T10271A

**Figure I15.1** - Nissan Vq30 Internal Ignitor Coil Wiring