

## MAP AND TPS PIN CONNECTIONS



FEEED SEALING RING ONTO WIRE,  
CRIMP PIN AND SEAL TO WIRE AND THEN INSERT INTO BACK OF PLUG